SHEP TODAY 07/Feb.

Work Order ID 96847 February-07-13 9:09:28 AM			*96847*							Page 1		
Item ID: Revision ID: Item Name:	D4012-1 Cushion			Accept	*N900	<b>040</b>	100	<b>)</b> *	Setup Sta	1/1	S1* S2*	
Start Date: Required Date Reference:	2/07/13 :: 2/07/13	Start Qty: 6.00 Req'd Qty: 6.00	*6* *6*		Cust Item I Customer:	D:				IN	<b>5</b> /	
Approvals:	Process QC:	Plan:	Date:			ate:		j	Run Sta Sto	171	R1* R2*	
Sequence ID/ Work Center I	I <b>D</b>	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	I	Revision Nbr										
D4012		3										
100	1 n h 1 n h 1 n n n n n n n n n n n n n		M.A	0.00	4)					,		
*100* Mill Conv		Мето		0.00	1.02/02/	104		6				
Conventional Milli	ing Machine	OC2 Inspect parts off p	SALVE FALVEAUR	an At	<b>-</b>							

120

QC8- Inspect parts - second check

Memo

0.00

0.00

\*120\*

\*11**0**\*

Quality Control

Memo

0.00

ord 13/02/07

6 12 \_\_\_\_

Quality Control

Packaging

Work Order ID 96847 Page 3 February-07-13 9:09:28 AM \*N900040100\* Item ID: D4012-1 Accept Setup Start **Revision ID:** Stop Item Name: Cushion **Start Date:** 2/07/13 Start Qty: 6.00 **Cust Item ID:** Required Date: 2/07/13 **Req'd Qty:** 6.00 **Customer:** Reference: Process Plan: **Approvals:** Date: **Tooling:** Date: Stop SPC (Y/N): QC: Date: \_\_\_\_\_ Date: Sequence ID/ **Tool ID** Tool # Plan Reject Operation Set Up/ Accept Reject Insp. **Work Center ID** Qty Number Stamp **Description** Code **Qty Run Hours** QC21- Final Inspection - Work Order Release 0.00 140 MUS 13-02-07 MWC 13-2-07 \*140\* QC 0.00 Memo Quality Control

Page 1

Work Order ID:

96847

Parent Item:

D4012-1

Parent Item Name:

Cushion

**Start Date: 2/07/13** 

Required Date: 2/07/13

Start Qty: 6.00

Required Qty: 6.00

**Comments:** 

IPP RevA: New issue 09.10.28 DD verified by:JLM

IPP RevB: revA as per dwg

09.11.18 DD verified by:JLM

by:JLM

ica by staivi	II I KCVD. I	cva as per dwg
PP Rev:C 11.01.10	as per dwg Rev.B	DD verified

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4287-3 UHMW U-Channel		Manufactured	No			100	f	14.4000	0.37	2.3368421			
				Location		Loc Qty	Lo	c Code		·	12/02/	6 M	76 P
				MAT051	MD	8				<u> </u>	3/02/	0 7 ,	/u.#
				<b>6</b> 49	40)	8			$-\frac{q_{t}}{2}$	Ø			
				ST202		6.4							
				911	02	6.4							

DART AEROSPACE LTD	Work Order: 96847	
		Ĩ
Description: Couching	Part Number: // 40/2-/	
Inspection Dwg: 04012 Rev: B	Page 1 of	1

## FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
4,41	+ 0.030	4,398	/		Vern	RA-26
0,17	± 0.030	0,145	V		11	/1
1, 25	± 0.030	0,145	<b>✓</b>		11	15
RO.031	± 0.010	0,034	<u> </u>		1,	(1
0,10	+ 0.030	0,103	<b>V</b>		( )	t ,
0,10	+0.010	1.053			1)	( \
0.076	± 0.030 ± 0.010 + 9.015	0,091			/1	( ]
·				<u> </u>		

Measured by:	M.D S	Audited by:	and	Preliminary Approval:	
Date:	13/02/07	Date:	13/02/17	Date:	

Rev	Date	Change	Revised by Approved
E	10.04.14	Added preliminary approval	KJ

